

EFC3610 i EFC5610 Frekventni regulatori

UPUTSTVO ZA BRZO PUŠTANJE U RAD

1. Početni uslovi

1.1 Ambijentalni radni uslovi

Radna ambijentalna temperatura	-10 ... 45°C
Temperatura skladištenja	-20 ... 60°C

1.2 Montaža

Način montaže	Vetrikalno na zid ili na DIN šinu
Minimalni prostor iznad uređaja	$d_{top} = 125 \text{ mm}$
Minimalni prostor ispod uređaja	$d_{bot} = 125 \text{ mm}$

1.3 Ožičenje

Napajanje	Povezati L1, L2, (L3) na napajanje
Motor	Povezati U, V, W na motor
Uzemljenje	Mora biti povezano
Širm	Mora biti povezan
Napojni kablovi	Vidi preporuke
Kontrolni terminali	Moraju biti povezani
Kontrolni kablovi	Vidi preporuke
Prekidači	Moraju biti isključeni

2. Osnovna podešavanja

2.1 Inicijalni parametri

b0.00	Autorizacija pristupa parametrima (<i>Default = 0</i>)
	0 – Vidljivi samo osnovni parametri (b0, d0, C0, E0, U0, U1)
	1 – Vidljivi i standardni parametri (C1, C2, C3, E5, E8)
	2 – Vidljivi i napredni parametri (E1, E2, E3, E4, E9)
	3 – <i>Start-up</i> parametri
	4 – Vidljivi izmenjeni parametri (parametri različiti od <i>default</i> vrednosti)
b0.10	Inicijalizacija parametara (<i>Default = 0</i>)
	0 – Neaktivno
	1 – Vraćanje na <i>default</i> vrednosti
	2 – Brisanje zapamćenih grešaka

2.2 Parametri motora

C1.05	Nominalna snaga motora	(0,1 ... 1000,0 kW)
C1.06	Nominalni napon motora	(0 ... 480 V)
C1.07	Nominalna struja motora	(0,01 ... 655,00 A)
C1.08	Nominalna frekvencija motora	(5,00 ... 400,00 Hz)
C1.09	Nominalna brzina motora	(1 ... 30.000 obr/min)

2.3 Parametri regulatora

C0.00	Način upravljanja za EFC 5610 (<i>Default = 0</i>)
	0 – V/F upravljanje
	1 – Vektorsko upravljanje
C0.01	Normal/Heavy duty za EFC 3610 (<i>Default = 1</i>)
	0 – <i>Normal duty</i>
	1 – Heavy duty

2.4 Parametri načina upravljanja

E0.00	Način zadavanja frekvencije (<i>Default = 0</i>)
	0 – Sa potenciometra na panelu
	1 – Sa tastera ↑ i ↓ na panelu
	2 – Sa AI1 analognog ulaza
	3 – Sa AI2 analognog ulaza
	10 – Sa X5 impulsnog ulaza
	11 – Sa digitalnih ulaza <i>Up/Down/Reset X1 ... X5</i>
	20 – Komunikacijom
	21 – <i>Multi-speed</i> zadavanje
E0.01	Način zadavanja komande (<i>Default = 0</i>)
	0 – Sa panela
	1 – Digitalnim ulazima
	2 – Komunikacijom
U0.01	Način rada STOP tastera (<i>Default = 1</i>)
	0 – Samo za način upravljanja sa panela
	1 – Za sve načine upravljanja

2.5 Parametri ograničenja brzine

E0.08	Maksimalna izlazna frekvencija (<i>Default</i> 50,00 Hz)
E0.09	Gornji limit izlazne frekvencije (<i>Default</i> 50,00 Hz)
E0.10	Donji limit izlazne frekvencije (<i>Default</i> 0,00 Hz)

2.6 Parametri ubrzanja/usporena

E0.25	Način ubrzanja/usporena (<i>Default</i> = 0)
	0 – Linearno
	1 – S krivina
E0.26	Vreme ubrzanja
E0.27	Vreme usporena
E0.28	Start faktor S krivine
E0.29	Stop faktor S krivine

2.7 Restart posle nestanka napajanja

E0.45	Tip reset-a posle nestanka napajanja (<i>Default</i> 0)
	0 - Neaktivno
	1 - Aktivno za upravljanje sa panela
	2 - Aktivno za upravljanje digitalnim ulazima
E0.46	Zadrška restarta posle nestanka napajanja (<i>Default</i> 1,00 s)

3. Konfigurisanje Ulaza i Izlaza

3.1 Digitalni ulazi

E1.00	X1 ulaz (<i>Default</i> = 0)	(0 ... 41)
E1.01	X2 ulaz (<i>Default</i> = 0)	(0 ... 41)
E1.02	X3 ulaz (<i>Default</i> = 0)	(0 ... 41)
E1.03	X4 ulaz (<i>Default</i> = 0)	(0 ... 41)
E1.04	X5 ulaz (<i>Default</i> = 0)	(0 ... 47)

0 – Bez funkcije

- 1 – *Multi-speed* komandni ulaz 1
- 2 – *Multi-speed* komandni ulaz 2
- 3 – *Multi-speed* komandni ulaz 3
- 4 – *Multi-speed* komandni ulaz 4
- 10 – Komandni ulaz ubrzavanje/usporenje 1
- 11 – Komandni ulaz ubrzavanje/usporenje 2
- 12 – Komandni ulaz ubrzavanje/usporenje 3
- 15 – Komanda Stop sa slobodnim zaustavljanjem
- 16 – Komanda Stop sa zaustavljanjem kočnicom
- 20 – Komanda povećanja frekvencije
- 21 – Komanda smanjenja frekvencije
- 22 – Komanda reseta povećanja/smanjenja frekvencije
- 23 – Kontrolni prekidač moment/brzina
- 25 – Trožična kontrola
- 26 – *Simple* PLC stop
- 27 – *Simple* PLC pauza
- 30 – Aktiviranje sekundarne zadate frekvencije
- 31 – Aktiviranje sekundarne start komande
- 32 – Signal greške NO kontakt
- 33 – Signal greške NC kontakt
- 34 – Reset grešaka
- 35 – Komanda napred
- 36 – Komanda nazad
- 37 – Skok na zadatu frekvenciju – napred
- 38 – Skok na zadatu frekvenciju – nazad
- 39 – Brojački ulaz
- 40 – Reset brojača
- 41 – Deaktivacija PID-a
- 47 – Aktiviranje impulsnog moda (samo za X5)

3.2 Analogni ulazi

E1.35	AI1 analogni ulaz (<i>Default</i> = 2)	(0 ... 4)
E1.40	AI2 analogni ulaz (<i>Default</i> = 1)	(0 ... 4)
	0 – 0 ... 20 mA	
	1 – 4 ... 20 mA	
	2 – 0 ... 10 V	
	3 – 0 ... 5 V	
	4 – 2 ... 10 V	


3.3 Digitalni izlazi

E2.01	DO1 digitalni izlaz (Default = 0)	(0 ... 20)
E2.15	Relejni izlaz (Default = 1)	(0 ... 20)
	0 – Konvertor spreman	
	1 – Konvertor radi	
	2 – Aktivna DC kočnica	
	3 – Konvertor radi na brzini 0 Hz	
	4 – Brzina blizu zadate	
	5 – Brzina iznad zadate granice 1 (FDT1)	
	6 – Brzina iznad zadate granice 2 (FDT2)	
	7 – Završen segment <i>Simple</i> PLC-a	
	8 – Završen ciklus <i>Simple</i> PLC-a	
	10 – DC bus napon niži od 230VAC/430VAC	
	11 – Upozorenje preopterećenje konvertora	
	12 – Upozorenje preopterećenje motora	
	13 – Stop usled eksterne greške	
	14 – Greška konvertora	
	15 – Konvertor OK	
	16 – Brojač blizu zadate vrednosti	
	17 – Brojač blizu srednje vrednosti	
	18 – PID referenca blizu zadate vrednosti	
	19 – Impulsi izlaz (samo za DO1)	
	20 – Režim kontrole momenta aktivan	

3.4 Analogni izlazi

E2.25	AO1 analogni izlaz (Default = 0)	(0 ... 1)
	0 – 0 ... 10 V	
	1 – 0 ... 20 mA	
E2.26	AO1 funkcija (Default = 0)	(0 ... 11)
	0 – Aktulena brzina (0,00 ... [E0.08])	
	1 – Zadata brzina (0,00 ... [E0.08])	
	2 – Izlazna struja (0 ... 2 x [nominalna struja])	
	4 – Izlazni napon (0 ... 1,2 x [nominalni napon])	
	5 – Izlazna snaga (0 ... 1,2 x [nominalna snaga])	
	6 – AI1	
	7 – AI2	
	8 – Napajanje temperturnog senzora motora	

4. Ožičenje



5. Prikaz na displeju

5.1 Prikaz vrednosti u Run i Stop režimu

U1.00	Prikaz u Run režimu	(0 ... 99) *
U1.10	X2 ulaz (Default = 0)	(0 ... 99) **
	0 – Output frequency *	
	1 – Actual speed	
	2 – Setting frequency **	
	3 – Setting speed	
	4 – User-defined setting speed	
	5 – User-defined actual speed	
	9 – V/f separation setting voltage	
	10 – Output voltage	
	11 – Output current	
	12 – Output power	
	13 – DC-bus voltage	
	14 – Energy saving counter kWh	
	15 – Energy saving counter MWh	
	16 – Output torque	
	17 – Setting torque	
	20 – Power module temperature	
	21 – Actual carrier frequency	
	23 – Power stage running time	
	30 – AI1 input	
	31 – AI2 input	
	33 – I/O card EAI1 input	
	34 – I/O card EAI2 input	
	35 – AO1 output	
	37 – I/O card EAO output	
	40 – Digital input 1	
	43 – I/O card digital input	
	45 – DO1 output	
	47 – I/O card EDO1 output	
	48 – I/O card EDO2 output	
	50 – Pulse input frequency	
	55 – PUlse output frequency	
	60 – Relay output	
	62 – I/O card relay output	
	63 – Relay card output	
	70 – PID reference engineering value	
	71 – PID feedback engineering value	
	80-89 – ASF display 00-09	
	98 – High resolution output current	
	99 – Firmware version	